

Certificate No: FM 769306

Location	Registered Activities
Component Coating & Repair Services Ltd Unit 1-4 Lydford Road Meadow Lane Industrial Estate Alfreton DE55 7RQ United Kingdom	Repair and overhaul of industrial gas turbine power units and their sub-components including component fabrication, Non-Destructive testing (Fluorescent Dye-Penetrant Inspection) and application of protective coatings
Component Coating & Repair Services Ltd Unit 5, Ecclesbourne Park Cotes Park Industrial Estate Alfreton DE55 7RF United Kingdom	Stripping, blasting, welding, machining, blending of blades, including thermal spray of land based gas turbine components and lab work

Original Registration Date: 2022-08-16

Effective Date: 2022-08-16

Latest Revision Date: 2022-08-16

Expiry Date: 2025-08-15

Page: 2 of 2

This certificate was issued electronically and remains the property of BSI and is bound by the conditions of contract.

An electronic certificate can be authenticated [online](#).

Printed copies can be validated at www.bsigroup.com/ClientDirectory

Information and Contact: BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP. Tel: + 44 345 080 9000
BSI Assurance UK Limited, registered in England under number 7805321 at 389 Chiswick High Road, London W4 4AL, UK.